


MODEL 230.4 as of 15.1.04

- 1 Beverage holder
2 Bolt



P68.10-3290-04

☒ ☒	Remove/install		
1	Loosen cover from center console until bolts (2) are accessible.	i Do not disconnect electrical connectors from center console cover.	AR68.20-P-2350RA
2	Unscrew bolts (2) and pull beverage holder (1) out of instrument panel.		
3	Install in the reverse order		